

RECEIVED

Revised 9/01

CORRES. CONTROL
INCOMING LTR NO.



2001 SEP 17 P 2:14 Department of Energy

CORRESPONDENCE
CONTROL

ROCKY FLATS FIELD OFFICE
10808 HIGHWAY 93, UNIT A
GOLDEN, COLORADO 80403-8200

SEP 12 2001

01-DOE-01538

DUE DATE
ACTION

DIST.	LTR	ENC
BOGENBERGER, V.		
BOGNAR, E.		
BRAILSFORD, M.D.		
BURNS, T. F.		
DECK, C. A.		
DIETERLE, S. E.		
FERRERA, D.W.	X	
FERRI, M.S.		
GERMAIN, A. L.		
GIACOMINI, J.		
HALL, L.		
ISOM, J. H.		
MARTINEZ, L.A.	X	
NORTH, K.		
PARKER, A.M.		
POWERS, K.		
RAAZ, R. D.		
RODGERS, A. D.		
SANDLIN, N. B.		
SCOTT, G.K.		
SHELTON, D.C.		
SPEARS, M.S.		
TRICE, K.D.		
TUOR, N.B.	X	
VOORHEIS, G.M.		
WILLIAMS, J. L.		
PARSONS, D.	X	
Gibbs, F.	X	

Mr. Steven H. Gunderson
Rocky Flats Cleanup Agreement Project Coordinator
Colorado Department of Public Health and Environment
4300 Cherry Creek Drive South
Denver, CO 80222-1530

Dear Mr. Gunderson:

Please find enclosed the Pre-Demolition Survey Report (PDSR) for Phase 1 of the Building 886 Cluster.

Your comments are welcome; however, approval of the whole report (Phase 1 and Phase 2) is not requested at this time. We do request your concurrence with the typing of Building 888 as a Type 1. This typing is supported by the enclosed report, which provides the reconnaissance level characterization (RLC) for that building. Approval of the whole PDSR will be requested when Phase 2 is submitted.

The following is provided as background to the enclosed report:

- An RLC was performed in the 886 Cluster in 1997. At the time of the 1997 RLC the 886 Cluster was defined as Buildings 886, 888A, 880, 875 and T886A. Although 888 is technically not apart of the 1997 RLC Cluster, the 1997 Reconnaissance Level Characterization Report (RLCR) did include some sample data for 888. The 886 Cluster - Phase 1 PDSR includes all of the buildings in the 1997 RLCR and 888. The 888 Cluster was included in the 886 Cluster - Phase 1 PDSR since it was an anticipated Type 1 facility and the Pre-Demolition Survey (PDS) that was performed in 888 was no different than what an RLC/PDS survey would have consisted of. The 888 PDS confirmed that the building is a Type 1 facility and can be demolished as such.
- The Building 886 Cluster - Phase 1 PDSR included the following areas in the 886 Cluster: 886 exterior, 875 exterior, T886A interior and exterior, 888 interior and exterior, 888A (transformer slab and block wall) exterior, and 886 Office Room interiors (i.e., Rooms 106, 111, 116-123, 125, and 127-131). The Phase 1 areas were surveyed because the rooms and areas were not anticipated to be contaminated and could be isolated from other areas of the Cluster that still need work (e.g., stripped out, decontaminated, etc.).
- The 886 Cluster - Phase 2 areas are defined as 886 interior rooms (i.e., Rooms 101-104, 108-110, 112-115, 126, 126A, 126B, 140, and 141), 875 interior, 880 interior and exterior, and 828 Pit. These Phase 2 rooms and areas are not yet ready for a PDS characterization and will be submitted in the future.

COR. CONTROL X X
ADMN. RECORD X
PATS/130

Reviewed for Addressee
Corres. Control RFP

9/12/01
Date *by*

Ref. Ltr. #

DOE ORDER #
NONE

DOCUMENT CLASSIFICATION
REVIEW WAIVER PER
CLASSIFICATION OFFICE



ADMIN RECORD

000035
B886-A-000035


1/2

Mr. Steven H. Gunderson
01-DOE-01538

2

SEP 12 2001

Questions can be directed to Steve Tower, Rocky Flats Field Office, Corporate Technical Group at (303) 966-2133.



Joseph A. Legare
Assistant Manager
for Environment and Stewardship

Enclosure

cc w/o Enc:

S. Tower, CTG, RFFO

D. Parsons, RISS

F. Gibbs, RISS

T. Rehder, EPA

Building 850 Administrative Record

2/2